
CSC Factory Production

Status of the CSC Factory Production at IHEP (China) and PNPI (Russia)

Oleg Prokofiev

Endcap Muon System

CMS Detector



Total Weight – 12,500 t Overall Diameter – 15.0m Overall Length – 21.6m Magnetic Field – 4.0Tesla 31 Nations

~150 Institutions


~ 2000 Scientists


EMU System Parameters

- 540 Cathode Strip Chambers (largest 3.4m x 1.5m)
- 6000 m² sensitive area
- 65 m³ gas volume
- 2 500 000 anode wires
- 150? m space resolution
- 25 ns bunch crossing resolution

CSC Chamber Design

Trapezoidal Six Layer Cathode Strip Chamber





Foreign Chamber Factory Production

According to MOU between US CMS Collaboration and Foreign Sites:

- PNPI (Russia) should construct 124 ME234/1 chambers
- IHEP (China) should construct 150 ME1/23 chambers
- IHEP and PNPI will provide chamber installation, commissioning and maintenance at CERN


US CMS Collaboration will provide:

- chamber parts and on-chamber parts
- critical tooling

EMU Chamber Production

FNAL Responsibility:

- ME234/2 chamber production (144 +2 spare)
- Panel production for all chambers (~3000 panels)
- Procurement (chamber parts, frame,...)
- Critical tooling for PNPI and IHEP
- Shipment On-Chamber parts



IHEP and PNPI Chamber Production Status

IHEP Status on CSC production (April 2002)

Chamber Production started on Jan. 1, 2002

Table 1: cumulative total

CSC Type	ME1/2 	ME1/3		
needed	74	74		
Assembled and tested	18	0		
Passed LT HV test	0	0		
Assembled With Elect.	0	0		
Passed Fast Site test	0	0		
Shipped to CERN	0	0		

PNPI Status on CSC production (April 2002)

Chamber Production started on Nov. 1, 2001

CSC	ME2/1	ME3/	1 ME4/1
needed	38	38	38
Assembled and Tested	24	0	0
Passed Long Term HV Test	: 0	0	0
Assembled with Electronics	0	0	0
Passed Long Term HV Test	: 0	0	0
Assembled with Electronics	0	0	0
Passed FAST Site Tests	0	0	0
Shipped to CERN	0	0	0

PNPI Chamber Tests

TABLE 2. CH/	====== AMBERS	FINISHED DU	JRING THE LAST MONTH at PNPI
CSC	Date finished	Leak Rate cc/min	CSC Current at 4.0 kV
ME2/1-018 19 20 21 22 23 24	03.04 10.04 15.04 18.04	0.13+/-0.22 -0.12+/-0.59 0.21+/-0.24 0.09+/-0.28 0.01+/-0.20 0.06+/-0.19 0.20+/-0.20	0.21 0.24 0.14 0.13 0.14 0.13 0.16

IHEP Chamber Tests

Table 2: chamber finished so far(Jan.1-Apr.30,2002):									
Chamber No	date dinish	ed Leak rate	current@4KV						
ME1/2-001	2/10/2002	1.11+-0.03	0.10						
ME1/2-003	2/11/2002	-0.05+-0.05	0.08						
ME1/2-004	2/12/2002	0.27+-0.12	0.10						
ME1/2-005	2/16/2002	0.68+-0.10	0.10						
ME1/2-006	3/14/2002	0.08+-0.07	0.10						
ME1/2-007	3/13/2002	0.34+-0.08	0.10						
ME1/2-008	3/15/2002	0.02+-0.06	0.10						
ME1/2-009	3/12/2002	0.26+-0.12	0.10						
ME1/2-010	3/11/2002	0.66+-0.12	0.11						
ME1/2-012	4/09/2002	0.97+-0.06	0.10						
ME1/2-013	4/13/2002	0.66+-0.11	0.10						
ME1/2-014	4/04/2002	0.89+-0.12	0.10						
ME1/2-015	4/03/2002	0.43+-0.21	0.10						
ME1/2-016	4/15/2002	0.28+-0.06	0.12						
ME1/2-017	4/14/2002	1.25+-0.10	0.10						
ME1/2-018	4/23/2002	0.33+-0.21	0.10						
ME1/2-019	4/24/2002	1.04+-0.15	0.15						
ME1/2-020	4/25/2002	0.47+-0.11	0.10						

IHEP Chamber Production Review

- Chamber factory production process
- Electrical tests
- Quality control, chamber parts inspection
- Travelers, discrepancy reports
- Conclusion

IHEP Factory Manpower

Factory personnel:

- Process engineer / flow manager (engineer) 1
- Panel cleaning, gluing, sealing, chamber assembly (technicians) 3
- Winding, wire soldering (technician) 1
- Hand soldering (technician) 2
- Tension, pitch, capacitance measurements (technician) 1
- HV panel tests and chamber tests (technician) 1
- Travelers, chamber assembly (technician) 1


Factory: 10 peoples + factory manager (physicist)

Material Storage









Cathode and Anode Panel Gluing









Panel Winding, Wire Gluing and Soldering







Hand Soldering, Chamber Assembly







IHEP Leak Measurements Results


The results of chamber leak rate measurements with the last five chambers

IHEP Chamber Leak Rate data													
Chamber	Date	? Time	Chamber Pressure		? ? P	Barometric Pressure		?	Temperature		? ?ूТ	Leak	? !Leak
#	(year/month/day)	(hours)	(inches of water)			(kF	Pa)	(kPa)	(C°)		(Co)	(cm ³ /min)	(cm ³ /min)
			Initial	Final		Initial	Final		Max	Min			
ME1/2-019	2002/4/12	23.5	2.6	2.9	-0.30	101.2	99.7	1.5	20.5	19.3	1.2	1.04	0.15
ME1/2-020	2002/4/10	23	2.68	2.87	-0.19	101.7	101	0.7	20.1	19.2	0.9	0.47	0.11
ME1/2-021	2002/4/15	23.2	2.58	1.94	0.64	100.7	100.6	0.1	20.9	19.9	1.0	0.40	0.12
ME1/2-022	2002/4/17	22	2.64	1.96	0.68	101.5	101.2	0.3	20.7	19.8	0.9	0.63	0.12
ME1/2-023	2002/4/18	22.5	2.51	2.37	0.14	101.3	100.8	0.5	20.5	19.8	0.7	0.52	0.09






Electrical tests






Panel Inspection







Travelers and Discrepancy Reports

Recommendation

- Need to fill travelers at time of production procedure.
- Pay more attention to filling out and complicity of travelers.
- Only a few discrepancy reports (DR) are available.
- Need to fill DR when chamber parts are out of technical specs.
- Fill DR for any sealed chamber which have to be repaired (taking apart).

IHEP Factory

Summary of production review at IHEP

- The CMS EMU group at IHEP has made excellent progress toward to the chamber production.
- During 3 months IHEP made more than 20 chambers and has reached the full rate chamber production (6 chamber per month).
- The results of the chamber tests meet the of technical specifications.
- The factory personnel demonstrated that IHEP team has achieved a good level of knowledge and experience on all aspects of their chamber production.

The next step – Production Review at PNPI, Russia in May, 2002